

FIG. 1




FIG. 1




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 4A

FIG. 4B is a schematic diagram of a test setup for measuring the transmission coefficient of a test sample.




FIG. 4B




FIG. 5




FIG. 6




FIG. 7A

540, 550




FIG. 7B




FIG. 8A

540, 550




FIG. 8B




FIG. 9A

540, 550




FIG. 9B




FIG. 10




FIG. 11




FIG. 12A




FIG. 12B




FIG. 12C